



Technical Information

Manual Washing of Clear and Tinted (Non-reflective Coated) Glass

Glass needs to be periodically washed to remove visible dirt and to prevent accumulations of dirt from bonding to or attacking the surface. ***Glass should be cleaned as frequently as is needed to keep its appearance acceptable.*** In some locations, and for some building owners, this cleaning will be more frequent than for others.

Glass is very durable when exposed to normal atmospheric conditions, but alkaline solutions, and some acids, can damage it. Cleaning materials from other parts of a building, or leaching and efflorescence from concrete, bricks and mortar, or run-off from oxidizing steel, can be particularly harmful. For this reason, it is important to prevent any visible accumulation of deposits from remaining on the glass surface where they can slowly attack it.

Some deposits may not be directly harmful in themselves but by retaining moisture they can cause glass staining and etching. Other deposits may cause damage indirectly simply by being so firmly attached to the glass that it is damaged by the overly aggressive cleaning actions needed to remove the deposits. When cleaning glass, note that there is usually a layer of abrasive dust resting lightly on the surface. The abrasiveness of this dust can easily scratch the glass if too much pressure is applied with too little cleaning solution. Proprietary window cleaning liquids, or dishwashing liquid detergents, such as Joy, Ivory or Dawn in low concentrations (10 to 15 drops per 3 to 4 gallons) can be used as cleaning solutions. Dried paint splashes on glass can be removed with paint solvents, followed by detergent and water washing, taking care that the solvents do not damage glazing materials and the frame. Careful use of the flat edge, not the corner, of a new safety razor blade can be used to remove paint drops from plain, non-coated annealed glass. Razor blades or any metallic scraper should not be used on heat strengthened or fully tempered glass as fine scratches which are only visible in full sunlight can be created.

Glasswerks Los Angeles
8600 Rheem Ave.
South Gate, CA 90280
Tel: 888.789.7810
Fax: 323.789.7857

Glasswerks Yuma
7595 E. 30th St.
Yuma, AZ 85365
Tel: 206.285.3140
Fax: 323.789.7820

Glasswerks Temecula
42005 Zevo Dr.
Temecula, CA 92590
Tel: 800.729.1324
Fax: 951.491.8254

Glasswerks Carson
642 E. Alondra Blvd.
Carson, CA 90746
Tel: 323.321.8806
Fax: 310.323.6969



Recommended Procedure for Manually Cleaning Glass:

- ☐ Commence cleaning as soon as the glass is visibly dirty.
- ☐ Avoid cleaning heat absorbing tinted glasses in direct sunlight, as the glass will be excessively hot for optimum cleaning.
- ☐ Flood the surface with water or cleaning solution to remove loose dust and grit.
- ☐ Hand wipe with clean wet cloths, using an approved detergent solution, until the glass is visibly clean.
- ☐ Rinse with clean water.
- ☐ Dry immediately with a clean lint-free cloth or squeegee. Do not allow metal squeegee holders to touch the glass surface.

The information contained in this bulletin is offered for assistance in the application flat glass products, but **IT DOES NOT CONSTITUTE A WARRANTY OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE.** Actual performance may vary in particular applications.

Glasswerks Los Angeles
8600 Rheem Ave.
South Gate, CA 90280
Tel: 888.789.7810
Fax: 323.789.7857

Glasswerks Yuma
7595 E. 30th St.
Yuma, AZ 85365
Tel: 206.285.3140
Fax: 323.789.7820

Glasswerks Temecula
42005 Zevo Dr.
Temecula, CA 92590
Tel: 800.729.1324
Fax: 951.491.8254

Glasswerks Carson
642 E. Alondra Blvd.
Carson, CA 90746
Tel: 323.321.8806
Fax: 310.323.6969